

## ECS Configuration Change Request

Page 1 of

Page(s)

1. Originator Maryellen Corbett	2. Log Date: 03/17/03	3. CCR #: 03-0190	4. Rev: —	5. Tel: 0703	6. Rm #: 2072C	7. Dept. SED
8. CCR Title: Removal of Tivoli from ECS Baseline and Hosts						
9. Originator Signature/Date Maryellen Corbett /s/ 03/17/03			10. Class II	11. Type: CCR	12. Need Date: 04-30-2003	
13. Office Manager Signature/Date Carolyn Whitaker /s/ 03/17/03			14. Category of Change: Initial ECS Baseline Doc.		15. Priority: (If "Emergency" fill in Block 27). Routine	
16. Documentation/Drawings Impacted (Review and submit checklist): See attached			17. Schedule Impact:		18. Cl(s) Affected:	
19. Release Affected by this Change: N/A		20. Date due to Customer:		21. Estimated Cost: None - Under 100K		
22. Source Reference: <input type="checkbox"/> NCR (attach) <input type="checkbox"/> Action Item <input type="checkbox"/> Tech Ref. <input type="checkbox"/> GSFC <input type="checkbox"/> Other:						
23. Problem: (use additional Sheets if necessary) The ECS Architect's Office has recommended that Tivoli software be removed from ECS configuration. The Government has reviewed this recommendation and has agreed to the removal. The Tivoli product currently has no maintenance support from the vendor. The older, non-baselined 3.6.x versions, installed at some sites would no longer be supported by the vendor even with maintenance. The Tivoli 3.6.x versions are also not certified for use with Sybase 12.5. NCRs 35990, 31593, 31806, 36388, 31681 are resolved with removal of this COTS product.						
24. Proposed Solution: (use additional sheets if necessary) Update the appropriate CM baseline documentation and remove all Tivoli software from ECS hosts. If removal is not planned for all installations at GSFC, an NCR should be submitted to reflect the intended baseline.						
25. Alternate Solution: (use additional sheets if necessary) None						
26. Consequences if Change(s) are not approved: (use additional sheets if necessary) Inconsistent baseline and installations						
27. Justification for Emergency (If Block 15 is "Emergency"):						
28. Site(s) Affected: <input type="checkbox"/> EDF <input checked="" type="checkbox"/> PVC <input checked="" type="checkbox"/> VATC <input checked="" type="checkbox"/> EDC <input checked="" type="checkbox"/> GSFC <input checked="" type="checkbox"/> LaRC <input checked="" type="checkbox"/> NSIDC <input checked="" type="checkbox"/> SMC <input type="checkbox"/> AK <input type="checkbox"/> JPL <input type="checkbox"/> EOC <input type="checkbox"/> IDG Test Cell <input type="checkbox"/> Other						
29. Board Comments:			30. Work Assigned To:		31. CCR Closed Date:	
32. EDF/SCDV CCB Chair (Sign/Date): Byron V. Peters /s/ 3/36/03			Disposition: <b>Approved</b> App/Com. Disapproved Withdraw Fwd/ESDIS ERB			
33. M&O CCB Chair (Sign/Date): Pamela Johnson /s/ 3/25/03			Disposition: <b>Approved</b> App/Com. Disapproved Withdraw Fwd/ESDIS Fwd/ECS			
34. ECS CCB Chair (Sign/Date):			Disposition: Approved App/Com. Disapproved Withdraw Fwd/ESDIS Fwd/ESDIS			

## ADDITIONAL SHEET

**CCR #:** 03-0190    **Rev:** -    **Originator:** Maryellen Corbett

**Telephone:** 0703    **Office:** 2072C

**Title of Change:** Removal of Tivoli from ECS Baseline and Hosts

CM Documents:  
COTS Version baseline 910-TDA-003  
Critical COTS List 910-TDA-023  
HW/SW Maps 920-TDx-002

and

Tivoli Impact Assessment Report provided to the Government

and

E-mail sent by Tonjua Hines confirming agreement to removal.

Architect's Office Comment:

Tivoli was cited in the ECS End-of-Contract (EOC) reconciliation for the Level 3 requirements listed below. All these requirements were successfully verified at EOC. ESDIS direction to remove Tivoli from the baseline was given after EOC and this action does not affect the EOC reconciliation in any way. Removal of Tivoli from the ECS baseline does not result in any ECS requirements liens.

DADS1300  
DADS1320  
DADS1330  
DADS1360  
DADS1380  
DADS1390  
DADS1470  
EOSD0780  
EOSD1703  
EOSD3000  
EOSD4100  
ESN-0620  
ESN-0640  
ESN-0650  
ESN-0690  
ESN-0740  
ESN-0750  
ESN-0760  
ESN-0780  
ESN-0790  
ESN-0800  
ESN-0810  
ESN-0830  
ESN-0840  
ESN-0900  
ESN-0910  
ESN-0920  
ESN-1000  
ESN-1060  
ESN-1070  
ESN-1090  
IMS-1650  
IMS-1760  
PGS-0420  
SMC-0340  
SMC-3300  
SMC-3370  
SMC-3380

SMC-3390  
SMC-3410  
SMC-3420  
SMC-4310  
SMC-4311  
SMC-4330  
SMC-5340  
SMC-8860

CM01AJA00 Revised 8/2/02

**ECS**